


## SWGGB Swage Inspection Gauge

A Swage inspection gauge is used to measure the depth of the swage compression. It is also used to determine what size tool is needed for the job.



### Ordering Information

AFL NO.	S.P.S.	DEPTH OF INSERTION		DIE SIZE
		MIN.	MAX.	
SWGGB100	1	1.5	2	65TD100
SWGGB150	1.5	1.5	2	65TD150
SWGGB200	2	2	2.5	65TD200
SWGGB250	2.5	2	2.5	65TD250
SWGGB300	3	3	3.5	65TD300
SWGGB350	3.5	3	3.5	65TD350
SWGGB400	4	3	3.5	65TD400
SWGGB500	5	5	5.75	85TD500
SWGGB600	6	6	6.75	115TD600